

8 equal intervals
16 equal intervals
32 equal intervals
true degree
Sampled phase winding
60
40
20
0
0
10
20
30
40
50
60
Map degree m in z^m